

WorldMark Palm Springs

1177 North Palm Canyon Drive
Palm Springs, CA 92262
Phone: (760) 416-4428
Fax: (760) 323-1766

Special Needs Unit Features

- Card key lock entry
- All entry doors have at least 33" of clearance
- All interior door widths 32"
- All doors have lever handles
- Two-bedroom has a 36"x36" roll-in shower
- 29" roll-under lavatories
- 17"-18" toilets
- Grab bars
- A portable bath bench with back support is available
- 24"-25" high beds
- Accessible patios
- Dining room table knee clearance 28"
- Minimum of 36" access on one bed side
- Front control stove/range
- Visual fire alarms

Resort Accessible Features

- Accessible parking
- Courtesy wheelchair
- TDD unit available
- Accessible routes to recreation and fitness center, outdoor pool, spa and children's pool

Palm Springs offers handicap parking and accessible routes to all resort facilities, including the outdoor swimming pool, spa, children's pool, game-room and fitness center. The special needs units are located on the ground floor and there is an elevator for access to units on upper floors. The resort has one TDD unit available. Visual fire alarms are available in all special needs units.

Special Needs Units

One bedroom, one bathroom
Two bedroom, two bathroom

All special needs units have card key lock entry, lever door handles and level thresholds. The one-bedroom unit has a 29" entry door, and the two-bedroom unit has a 33" entry door. Units have interior door widths of at least 32". Bathrooms are equipped with grab bars, 17"-18" toilets, 29" of knee clearance under lavatories and tub/showers with grab bars and shower curtains. In addition, the two-bedroom unit has a 36"x36" roll-in shower. A portable bath bench with back support is also available. Bedrooms have at least 36" of clearance on one bed side. The kitchens have front control stoves/ranges. Living areas are accessible, and the patios have at least 30" access, thresholds from 1" - 1½" and patio tables with 28" of knee clearance.

No standard units at this property are recommended for mobility impaired guests because doorways are as narrow as 26" and the bathrooms are too small to accommodate wheelchairs.

Photos are from special needs two-bedroom unit

