

WorldMark Pismo Beach

100 Ocean View Avenue
Pismo Beach, CA 93449
Phone: (805) 773-4994
Fax: (805) 773-0924

Special Needs Unit Features

- Entry and interior doors have 33" of clearance
- Bed access is 38" on one side and 34" on the other
- Bed height is very tall at 29"
- Limited access dining table knee clearance: 28½" with only 11" depth
- 36"x 37" roll-in shower
- Grab bars
- Handheld showerhead
- Fold-down shower bench
- Limited access roll-under lavatory knee clearance: 27" with only 11" depth
- 17" toilets
- Visual fire alarms

Resort Accessible Features

- Accessible parking
- Card key locks
- Accessible routes to all facilities
- Lift for spa access
- Compliance kit with TDD unit and visual alarms for fire, phone and door knock available

WorldMark Pismo Beach is located on level to gently sloping property and has handicap designated parking. There are accessible routes to all facilities. There is a lift available for outdoor spa access.

Special Needs Units

One-bedroom, one-bathroom

The special needs unit has card key lock entry, lever door handles, level thresholds and 33" entry clearance. Interior doorways for the accessible bedroom and bathroom have 32" of clearance. The special needs bathroom is equipped with grab bars, a 17" high toilet with 27" of knee clearance under the lavatory and only 11" depth, making it only partially accessible. The 36"x 37" roll-in shower has a handheld showerhead and fold down seat. The accessible bedroom has a queen bed with 38" access on one bed side and 34" on the other. Kitchen has a rear control oven/stove, 34" counters and a 34" high sink with 26½" roll-under feature with only 11" depth, making it only partially accessible. Dining room tables have 28½" knee clearance with only 11" depth, making it only partially accessible. Living areas are small but accessible, as is the 7'x 7' patio.

Only nine of the standard units have ground floor access. None of them are recommended for mobility impaired guests because access to the entries is difficult and bathrooms are too small to accommodate most wheelchairs.

Photos are from special needs one-bedroom unit



This guide was researched and compiled by WorldMark owners Larry and Rachelle Topliff. Their company, Accessible Solutions, helps businesses provide better access for all.